

Wrong Way Wednesday | Feb. 24, 2015



Solution:



“Hey! Where do we keep the extra paper towels?”

There’s a lot going wrong in this issue of Wrong Way Wednesday. Unfortunately, I don’t know what event led up to the mess in the image. I’d like to think that it has something to do with Ninjas and/or cyborgs but we may never know the whole truth.

Regardless, there are at least two issues that we can address: (1) An unstable support system for the fallen IBC tank. (2) An insufficient spill response.

(1) The Ultra-IBC Spill Pallet has an engineered support system that can support up to 16,000 lbs. (UDL) so your customer can be sure that their IBC totes are secure and stable.

(2) I’m not sure what the sorbent socks in the picture are supposed to be doing but it certainly doesn’t look like it’s containing the spill. The Ultra-Spill Berm is a 10-foot long, urethane dike that is perfect for containing spills like these and making sure they don’t reach sensitive areas, equipment or drains.

And now you know. Happy Wednesday!